



The State of New Hampshire  
**DEPARTMENT OF ENVIRONMENTAL SERVICES**



**Thomas S. Burack, Commissioner**

**VIA EMAIL ONLY**

April 20, 2015

James Presher, PE, Director  
Concord Regional Solid Waste /Resource Recovery Cooperative  
PO Box 157  
Franklin, NH 03235  
Email: [crswrrc@aol.com](mailto:crswrrc@aol.com)

**SUBJECT: FRANKLIN- Franklin Secure Residue Landfill, Punch Brook Road; Type II Permit Modification and Waiver Applications for Stage II Closure Construction, Permit #DPHS-SW-85-003, prepared by CMA Engineers, Inc.; Ref.: WMD Doc Log # 16057**

Dear Mr. Presher:

The New Hampshire Department of Environmental Services, Waste Management Division (Department) has completed a review of the above-cited Types IB and II permit modification applications. In accordance with the requirements of the New Hampshire Solid Waste Rules (Rules), the following information must be provided to satisfy the provisions of Env-Sw 304.03 for a completeness determination, and Env-Sw 304.07, Env-Sw 202, and Env-Sw 315 for a technical review.

**Completeness**

1. The seasonal restrictions required in Env-Sw 1104.04 cannot be found. Please explain.

**Application**

2. The Section 1.0 mentions the landfill stopped receiving waste on December 31, 2015. Please explain.
3. Section 3.0 the Application mentions the bottom layer of the cap will be 12" of loam; however, in the next paragraph it is mentioned that the buffer layer over the waste is being requested to waive. According to Env-Sw 805.10(e), this means a sand layer would be used, which coincides with Detail A on Sheet 6. Please explain.
4. In Section 3.0, the 12" layer of loam at the top of the cap mentioned in the 3<sup>rd</sup> paragraph is not shown in the layers mentioned in the 1<sup>st</sup> paragraph. Please explain.

[www.des.nh.gov](http://www.des.nh.gov)  
29 Hazen Drive • PO Box 95 • Concord, NH 03302-0095  
(603) 271-2925 • TDD Access: Relay NH 1-800-735-2964



Jim Presher, PE, Director  
Franklin Secure Residue Landfill  
April 20, 2015  
Page 2 of 2

### Drainage

5. In Appendix B, Sheet 3- AoT Post Development Drainage Plan, shows a Drainage Swale 5; however, this swale could not be found in the Channel Results table. Please explain.
6. The SN Element IDs in the Junction Results table cannot be found on a site plan. Please explain.

### Waiver

7. The Property Site Plan shows map/lot #83/009, 83/010, and 82/401 abutting the property; however, no notifications can be found for them. Also, Note (4) mentions parcel 82/409; however, this parcel cannot be found. Please explain.

### Plans

8. Details K and R on Sheet 8 reference Sheet 3 and 2, respectively; however, callouts for these details cannot be found on these sheets. Please explain.
9. On Detail O Sheet 8, please show the capping system.

Please address the above comments by submitting one copy of the required information. Be certain to note the revision date on each replacement page. Continued review of your application will commence upon receipt of this information.

Until the Department has completed its completeness and technical reviews, there may be additional comments. In the meantime, if you have any questions, please contact me.

Sincerely,



Paul M. Gildersleeve, P.E.  
Solid Waste Management Bureau  
Tel: (603) 271-2935  
Fax: (603) 271-2456  
[E-mail: paul.gildersleeve@des.nh.gov](mailto:paul.gildersleeve@des.nh.gov)

ec: Wayne Wheeler, PE, NHDES, [Email: wayne.wheeler@des.nh.gov](mailto:wayne.wheeler@des.nh.gov)  
Melanie Doiron, NHDES, [Email: melanie.doiron@des.nh.gov](mailto:melanie.doiron@des.nh.gov)  
Elizabeth Dragon, City Manager, City of Franklin, [Email: citymgr@franklinnh.org](mailto:citymgr@franklinnh.org)  
Paul Schmidt, PE, CMA Engineers, [Email: pschmidt@cmaengineers.com](mailto:pschmidt@cmaengineers.com)